

INTEGRATION FROM HELIOS

Keep the warranty & keep your customer - with 1 click!

Service with 1 click.

With Helios and Digital-Servicebook.com integration, it is never easier to make service registration correctly and digitally.

The screenshot displays a 'Salgsordre' (Sales Order) window. A red arrow points to the button 'Send data til Digital Servicebog' in the top right corner. The window contains the following information:

- Customer Information:** Ordrenr. 28455, Ordredato 020918, Basisnr. 5084, Reg.nr. BY92196, Mærke AUDI, Model A 4 AVANT 2.0 TDI.
- Order Details:** Faktura, Ordrenr. 28455, Rekv.nr., Fakturanr. 25430, Fakturadato 020918, Typegodk.nr. E52128-02.
- Item Table:**


Vare	Varenummer	Tekst	Antal	Salgspris	Rabat %	Total	Vare status
Vare		105.000 eftersyn	0	0,00	0,00	0,00	Udefineret
Vare		+ 2 nye dæk	0	0,00	0,00	0,00	Udefineret
Vare		+ V forlyrs pære udsk	0	0,00	0,00	0,00	Udefineret
Vare		+ 4 hjulsudmåling	0	0,00	0,00	0,00	Udefineret
Vare	14129318	Selenia WR P E 5w-30	0	0,00	0,00	0,00	Udefineret
Vare	T00247	ENERGIFGIFT + CO2 1L	0	0,00	0,00	0,00	Udefineret
Vare	27CA10522	LUFFILTER	4,3	174,00	0,00	748,20	Udefineret
Vare	27CF10457	POLLENFILTER	4,3	2,97	0,00	12,77	Udefineret
Vare	27-CH9463AECO	OLIEFILTER INDSATS	1	206,80	0,00	206,80	På lager
			1	259,60	0,00	259,60	På lager
			1	99,00	0,00	99,00	Bestilt

Summary: Brutto 4.450,27, Rabat 0,00, Netto 4.450,27, Moms 1.112,57, Total 5.562,84.



DIGITAL-SERVICEBOOK.COM

The customer receives SMS with free access



All invoice data (without personal data and without price) is now online to the customer.

Search Workshop Customers Service plan OE data Reparation photos Notifications 0 My profile Support Log out Back to Admin# Language

VW POLO 1,4/80

Västberga Plåt och Lack AB
Elektravägen 43 Elektravägen 43
12630 Hägersten

Model: VW POLO 1,4/80
Reg. no.: ACD710
VIN no.: WVVZZZ9NZ8D012048
Mileage: 115728
Date: 2018-11-08
Invoice nr.: 101046

Comment

Service vid 36 mnader oavsett km och sedan var 2

Service var 60000e km eller 48e mnad

Service kombinerad intervallservice och inspektio

Arbete

Part number	Description	Quantity
18-FR7HC	Tndstift bosch	4
15-OC295	Oljefilter	1
15-2201255	Oljeplugg med packning	1
15-LX2010	Luftfilter	1
15-LAK120	Kupfilter kol	1
41-706402	Bromsvtska ate dot4 sl6	1
41-C4003009	Motor castrol edge fst ti helsyntet 5w-30	3,2
25-V10-2208	Torkarm bak	1
AF_B	Assistansfrskring bas	1

Service is registered

Search

[Car info](#) [Specifications](#) [Service book](#) [Service plan](#) [Inspection](#) [Debt](#) [Insurance](#) [Taxes](#)

Paper service books and online service data can be uploaded to Digital-Servicebook.com

Date	Car	Type	Mileage	Workshop	Comment	Report
08/11/2018	VW POLO 1,4/80	Service / Repair	115728	Västberga Plåt och Lack AB	Service vid 36 mnader oavsett km och sedan var 2, Service var 60000e km eller 48e mnad, Service kombinerad intervallservice och inspektio, Arbete	<input type="button" value="Show"/>